

2010 Lidar
Accuracy Assessment and
Quality Control Report
For the Milwaukee, WI
Project Area

December 1, 2010

Prepared for:

Milwaukee County Land Information Office
Milwaukee County Department of Transportation and Public Works
City Campus - Room 426
2711 W Wells St.
Milwaukee, WI. 53208
414.278.2176 phone

Prepared by:

Groundpoint Technologies, LLC
14 Lund Court
Woodstock, NY 12498
(845) 679-9223

1. Table of Contents

| | | |
|---------|---|----|
| 2. | INTRODUCTION | 4 |
| 3. | Accuracy Assessment | 6 |
| 3.1 | Lidar Checkpoint Ground Survey Data | 6 |
| 3.2 | Lidar Data | 7 |
| 3.3 | Checkpoint Survey/Lidar Data Post-Processing..... | 8 |
| 3.4 | Randomly Spaced Lidar Accuracy Assessment Methodology | 8 |
| 3.5 | Overall Statistics for the Randomly Spaced Lidar Data | 9 |
| 3.6 | ACCURACY ASSESSMENT SUMMARY | 15 |
| 4. | QUALITY CONTROL REVIEW | 15 |
| 4.1 | Deliverables Review | 15 |
| 4.1.1 | Verify Pre-Flight Deliverables | 15 |
| 4.1.2 | Verify Post-Flight Deliverables | 15 |
| 4.1.3 | Verify Mission Documentation..... | 16 |
| 4.1.3.1 | Calibration Report | 16 |
| 4.1.3.2 | PDOP | 16 |
| 4.1.3.3 | Base Station | 16 |
| 4.1.3.4 | Mission Report | 16 |
| 4.1.3.5 | Flight Lines..... | 16 |
| 4.2 | General Data Review | 17 |
| 4.2.1 | Total Number of Points | 17 |
| 4.2.2 | Collection Area | 18 |
| 4.2.2.1 | Datum | 18 |
| 4.2.2.2 | Round-Off Check | 18 |
| 4.2.2.3 | Edge Consistency | 19 |
| 4.2.2.4 | Mosaic/Hillshade | 19 |
| 4.2.3 | Complete Coverage | 19 |
| 4.2.3.1 | Metadata Complete..... | 20 |
| 4.3 | Technical Data Review | 20 |
| 4.3.1 | Range of Elevations | 20 |

| | | |
|-------|---|----|
| 4.3.2 | Bare Earth Point Density and Post Spacing | 20 |
| 4.3.3 | Void Areas..... | 20 |
| 4.3.4 | Artifacts..... | 21 |
| 5. | Summary..... | 22 |
| 6. | References | 22 |
| | Appendix A..... | 23 |

List of Figures

| | | |
|----------|---|----|
| Figure 1 | Boundary of the 2010 lidar Milwaukee, WI collection area. | 4 |
| Figure 2 | Distribution of surveyed checkpoints by landcover class. | 7 |
| Figure 3 | Distribution of all lidar points in the Milwaukee, WI collection area..... | 8 |
| Figure 4 | Example of a checkpoint in the Brush land cover type displayed with a TIN. | 9 |
| Figure 5 | Histogram showing the distribution of error residuals. | 10 |
| Figure 6 | Flightlines for the collection area. | 17 |
| Figure 7 | Lidar Tile Index..... | 18 |
| Figure 8 | Hillshade example displayed at 1:4000 scale. | 19 |

List of Tables

| | | |
|----------|--|----|
| Table 1. | Error Residuals between Checkpoint Z value and Lidar Z value..... | 11 |
| Table 2. | Summary Error Residual Statistics (Lidar Surface - Checkpoint Data) | 13 |
| Table 3. | Summary of Error Residual Statistics for All the Checkpoints and for the Checkpoints Classified by Land Cover Type. | 14 |
| Table 4 | Supplemental Vertical Accuracy of all land cover types..... | 14 |

2. INTRODUCTION

Lidar-based elevation data may be used for hydraulic modeling and floodplain mapping if it meets specific quality assurance and quality control criteria (FEMA 2003). GroundPoint Technologies LLC (Groundpoint) performed an independent accuracy assessment and quality control review of the bare-earth randomly spaced Lidar data collected in Milwaukee, Wisconsin. The methodology was designed to meet FEMA guidelines and specifications for flood mapping (FEMA, 2003). This document presents the results of the accuracy assessment and quality review.

Lidar data for Milwaukee, WI was collected by Pictometry International Corp (Pictometry) in 5 missions from April 16-18, 2010. The data was collected at a nominal post spacing of 70 centimeters over an area covering approximately 245 square miles (see Figure 1).




Figure 1 shows the boundary of the 2010 lidar Milwaukee, WI collection area. Pictometry processed the raw point cloud data to ensure proper alignment of the data between flight lines. The data was then classified for “Ground” by using a series of automated filters in

Terra Solid software to remove above ground vegetation and buildings. Points in water and on bridges were manually removed from the Ground class. The data was then tiled and saved in the industry standard LAS 1.2 format. The data was delivered on an external hard drive to Groundpoint in classified LAS format in the summer of 2010.

A Lidar checkpoint ground survey was also contracted by Pictometry for the accuracy assessment of the data. The survey consisted of 100 checkpoints in five different land cover types. The elevation values of the checkpoints are compared to the lidar data elevation values. The elevation differences are used to calculate the root-mean-square error (RMSE) of the data. FEMA provides guidelines and specifications for assessing the accuracy of lidar data that will be used for flood hazard mapping for the 2-foot (flat terrain in the floodplain) and 4ft (hilly terrain) contour intervals (FEMA, 2003). The data meets FEMA specifications for two foot contour mapping if the RMSE is no greater than 18.5 centimeters (7.2834 inches) and the error residuals have a normal distribution. The Milwaukee, WI data was captured with a specification for meeting accuracy standards at a 1-foot contour interval. Therefore the updated FEMA guidelines of September 2010 will be used for the vertical accuracy assessment reference of this lidar data. The updated guidelines will not be used for the rest of the project since the guidelines were published after the rest of the QAQC work was completed. The updated guidelines refer to the National Digital Elevation Program guidelines from 2004 for determining the accuracy of lidar data. The NDEP guidelines state that lidar data collected for 1 ft contour mapping will meet fundamental accuracy specifications for open ground if the RMSE is no greater than 9.25 centimeters (3.642 inches) and the error residuals have a normal distributions. The guidelines also state that supplemental accuracy for other land cover types will be calculated at the 95th percentile. RMSE should not be used for land cover types other than open ground since these land cover types often do not display a normal error distribution. Because these guidelines came out when this project was nearing completion, both RMSE and 95th percentile will be calculated for the supplemental accuracy. The accuracy assessment methodology and results are reported in section 3 Accuracy Assessment. ***The fundamental accuracy assessment for the Milwaukee, WI lidar collection meets the RMSE specifications for 1 foot contour mapping in open ground.***

In addition to performing an accuracy assessment, Groundpoint visually inspected the Ground lidar points to assess the completeness and consistency of the dataset, which may not be captured during the accuracy assessment. The visual inspection of the data is reported in section 4 Quality Control Review. ***A few minor problems were discovered during the Quality Control Review. These problems were communicated to Pictometry and corrected.***

3. Accuracy Assessment

Groundpoint utilized a methodology for assessing the accuracy of the randomly spaced Lidar data that is compliant with FEMA and specifications and supplemented with NDEP specifications for the 1 ft contour interval.

3.1 Lidar Checkpoint Ground Survey Data

A Lidar checkpoint ground survey was provided by Pictometry.

The surveyor collected a total of 100 points in the following cover types:

1. Bare-earth (e.g., plowed fields, lawns, golf courses), 21 Checkpoints
2. High Grass, Weeds, and Crops (e.g., overgrown fields and hay) 22 Checkpoints
3. Brush lands and low trees (e.g., scrubby low trees and bushes), 16 Checkpoints
4. Forested (e.g., hay fields, corn fields, wheat fields), 21 Checkpoints
5. Urban areas (e.g., high, dense manmade structures), 20 Checkpoints




Figure 2 shows the distribution of surveyed checkpoints by landcover class.

FEMA recommends 20 survey points per class. The brush lands and low trees class only has 16 checkpoints but all other classes have 20 or more checkpoints. Statistics were still calculated for the brush class, but it should be noted that the sample size does not meet FEMA guidelines. Digital photos and field sketches are also required for each checkpoint and the surrounding area to verify land cover and other conditions. All of the points include field sketches and photos taken in 4 directions from the surveyed checkpoint.

The Lidar Checkpoint Survey Data for the collection area is available in Appendix A. The Northing and Easting (Y and X) points are in NAD27, State Plane Coordinate zone Wisconsin South, feet, and the elevation (Z) is in NAVD 88, Geoid 2003, feet. The coordinate system of the survey points corresponds to the coordinate system of the lidar data.

3.2 Lidar Data

The Lidar data was delivered by Pictometry via an external hard drive. There are 319 Lidar tiles, all in LAS format. The LAS files contain all points classified as either "Unclassified",

“Ground”, “Overlap”, and “Low Point”. The data was delivered in NAD27, State Plane Wisconsin South horizontal coordinate reference system and NAVD88 vertical datum adjusted to GEOID '03 (all units in feet).

3.3 Checkpoint Survey/Lidar Data Post-Processing

The checkpoint survey data was delivered in excel format. The excel file was converted to a shapefile and brought into an ESRI ArcMap project along with the Lidar collection area index. The checkpoints were well distributed throughout the region (See Figure 3 below). Groundpoint used LP360 software, a plugin for ArcGIS, to perform the accuracy assessment.




Figure 3 shows the distribution of all lidar points in the Milwaukee, WI collection area.

3.4 Randomly Spaced Lidar Accuracy Assessment Methodology

In order to compare the elevation values of the checkpoints to the Lidar data a TIN surface was created from the Lidar points and a point shapefile was created from the XYZ values of the table of checkpoints. A TIN is a 3D surface that preserves the precision of the Lidar data points while simultaneously modeling the values between the points. Figure 4 shows an example of the TIN created for performing the accuracy assessment from the check point survey.




Figure 4 shows a checkpoint in the Brush land cover type displayed with a TIN created from the lidar ground points in the top image. The TIN colors indicate elevation range. The bottom image shows the same checkpoint displayed with orthoimagery provided by Milwaukee.

LP360 software tools and Microsoft Excel were used to implement a randomly spaced Lidar accuracy assessment. LP360 was used to compute spot elevations from the TIN surface at the location of each survey point. The results were exported to a text file and brought into Microsoft Excel for the statistical analysis.

3.5 Overall Statistics for the Randomly Spaced Lidar Data

For floodplain mapping, NDEP specifies the vertical accuracy of the data must have a root-mean-square error (RMSE) no greater than 9.25 centimeters (3.641 inches or 0.303 feet) for

normally distributed data. This is equivalent to 1-foot contour interval mapping. RMSE is the square root of the average of the squared elevation differences between data set elevation values and checkpoint elevation values for identical points.

$$RMSE = \sqrt{\frac{\sum (Lidar_z - Checkpoint_z)^2}{n}}$$

The data is checked for a normal distribution by using a frequency histogram and measures of kurtosis and skew. Kurtosis describes the curve of the distribution; whether it is more flat or peaked than normal. The skew gives an indication of whether there are systematic errors or biases in the data, which would make the curve lopsided. Data with a normal distribution has a bell shape on the frequency histogram with a zero mean, zero kurtosis, and zero skew. Lidar data rarely meets these three criteria exactly for a normal distribution; therefore FEMA specifies limits for Kurtosis and Skew.

The collection area data does meet FEMA specifications for a normal distribution (See Figure 5). The mean elevation difference is -0.187 ft (-5.70 cm) meaning the lidar data elevation values are on average below true ground elevation values. The standard deviation is 0.186 ft therefore 95% of the elevation differences should fall between -0.559ft and 0.186 ft (-17.038 cm and 5.66 cm).




Figure 5 is a histogram showing the distribution of error residuals. A “normal” shaped histogram would be bell shaped and centered on zero. This histogram is not bell shaped, but within the limits of the FEMA specification for normally distributed lidar data.

The shape of the curve is flatter than normal with a Kurtosis of -0.395. The error distribution is skewed slightly to the right with a Skew of 0.025. FEMA recommends any skew value exceeding the absolute value of 0.5 be investigated to determine whether there is a valid reason why the errors do not have a normal distribution since the RMSE calculation is only valid on data with a normal distribution. This data meets the FEMA criteria for a normal distribution

The set of elevation residual differences (between survey and Lidar elevations) for 100 survey points was processed and the results of the statistical analysis are shown in table 2. The survey checkpoints are considered to be “true ground”. When the resulting error residual is positive the lidar data is above true ground. When the resulting error residual is negative then the lidar data is below true ground. Using all land cover types, the average elevation difference is negative with an overall average of -0.187 ft (-5.70 cm). Table 1 contains the Z value of all the points by landcover type, the checkpoint Z value and the error residual (Lidar_Z – Checkpoint_Z).

Table 1. Error Residuals between Checkpoint Z value and Lidar Z value.

| Checkpoint | Checkpoint _Z | Lidar _Z | LidarZ - Checkpoint _Z | Checkpoint | Checkpoint _Z | Lidar _Z | LidarZ - Checkpoint _Z |
|------------|-------------------------|--------------------|----------------------------------|------------|-------------------------|--------------------|----------------------------------|
| BareEarth | 675.215 | 675.585 | -0.37 | Brush | 709.93 | 710.094 | -0.164 |
| BareEarth | 702.828 | 703.162 | -0.334 | Brush | 721.193 | 721.357 | -0.164 |
| BareEarth | 797.271 | 797.664 | -0.393 | Brush | 649.371 | 649.657 | -0.286 |
| BareEarth | 718.773 | 719.074 | -0.301 | Brush | 644.932 | 645.392 | -0.46 |
| BareEarth | 721.531 | 721.751 | -0.22 | Brush | 704.144 | 704.466 | -0.322 |
| BareEarth | 765.984 | 766.171 | -0.187 | Brush | 651.937 | 651.951 | -0.014 |
| BareEarth | 784.056 | 784.358 | -0.302 | Brush | 733.484 | 733.761 | -0.277 |
| BareEarth | 615.434 | 615.9 | -0.466 | Brush | 679.358 | 679.668 | -0.31 |
| BareEarth | 689.414 | 689.529 | -0.115 | Brush | 684.631 | 684.922 | -0.291 |
| BareEarth | 683.564 | 683.536 | 0.028 | Forested | 740.62 | 740.672 | -0.052 |
| BareEarth | 587.729 | 588.039 | -0.31 | Forested | 670.209 | 670.677 | -0.468 |
| BareEarth | 701.29 | 701.661 | -0.371 | Forested | 767.24 | 767.424 | -0.184 |
| BareEarth | 703.863 | 704.07 | -0.207 | Forested | 715.013 | 714.94 | 0.073 |
| BareEarth | 756.369 | 756.425 | -0.056 | Forested | 732.72 | 732.909 | -0.189 |
| BareEarth | 656.87 | 657.189 | -0.319 | Forested | 826.284 | 826.432 | -0.148 |
| BareEarth | 691.083 | 691.451 | -0.368 | Forested | 657.703 | 657.676 | 0.027 |
| BareEarth | 654.598 | 654.691 | -0.093 | Forested | 627.682 | 627.947 | -0.265 |
| BareEarth | 692.402 | 692.417 | -0.015 | Forested | 758.203 | 758.315 | -0.112 |
| BareEarth | 685.571 | 685.897 | -0.326 | Forested | 659.512 | 659.412 | 0.1 |
| BareEarth | 662.188 | 662.634 | -0.446 | Forested | 700.039 | 700.023 | 0.016 |
| BareEarth | 689.82 | 689.679 | 0.141 | Forested | 717.446 | 717.518 | -0.072 |
| Tall Grass | 761.793 | 761.952 | -0.159 | Forested | 670.641 | 670.514 | 0.127 |
| Tall Grass | 728.027 | 728.11 | -0.083 | Forested | 675.04 | 675.014 | 0.026 |
| Tall Grass | 740.997 | 741.573 | -0.576 | Forested | 708.64 | 708.999 | -0.359 |
| Tall Grass | 732.702 | 733.118 | -0.416 | Forested | 706.116 | 706.367 | -0.251 |
| Tall Grass | 691.788 | 692.123 | -0.335 | Forested | 705.677 | 705.65 | 0.027 |
| Tall Grass | 735.508 | 735.979 | -0.471 | Forested | 757.5 | 757.569 | -0.069 |
| Tall Grass | 651.684 | 652.137 | -0.453 | Forested | 659.464 | 659.902 | -0.438 |

2010 Lidar Accuracy Assessment and Quality Control Report
December 2, 2010

| Checkpoint | Checkpoint _z | Lidar _z | LidarZ - Checkpoint _z | Checkpoint | Checkpoint _z | Lidar _z | LidarZ - Checkpoint _z |
|------------|-------------------------|--------------------|-------------------------------------|------------|-------------------------|--------------------|-------------------------------------|
| Tall Grass | 669.936 | 670.34 | -0.404 | Forested | 743.911 | 743.994 | -0.083 |
| Tall Grass | 754.133 | 754.356 | -0.223 | Forested | 779.074 | 779.231 | -0.157 |
| Tall Grass | 730.938 | 731.253 | -0.315 | Urban | 822.094 | 822.075 | 0.019 |
| Tall Grass | 598.696 | 599.074 | -0.378 | Urban | 679.874 | 679.816 | 0.058 |
| Tall Grass | 757.803 | 757.859 | -0.056 | Urban | 668.126 | 668.144 | -0.018 |
| Tall Grass | 680.426 | 680.562 | -0.136 | Urban | 775.918 | 775.604 | 0.314 |
| Tall Grass | 671.328 | 671.598 | -0.27 | Urban | 679.433 | 679.404 | 0.029 |
| Tall Grass | 716.745 | 716.771 | -0.026 | Urban | 717.497 | 717.63 | -0.133 |
| Tall Grass | 662.567 | 662.537 | 0.03 | Urban | 700.447 | 700.612 | -0.165 |
| Tall Grass | 694.783 | 695.192 | -0.409 | Urban | 741.839 | 741.921 | -0.082 |
| Tall Grass | 737.726 | 738.024 | -0.298 | Urban | 819.13 | 819.05 | 0.08 |
| Tall Grass | 782.428 | 782.627 | -0.199 | Urban | 732.768 | 732.781 | -0.013 |
| Tall Grass | 750.235 | 750.3 | -0.065 | Urban | 765.041 | 764.896 | 0.145 |
| Tall Grass | 753.887 | 754.206 | -0.319 | Urban | 708.497 | 708.47 | 0.027 |
| Tall Grass | 769.169 | 769.506 | -0.337 | Urban | 597.307 | 597.358 | -0.051 |
| Brush | 682.248 | 682.573 | -0.325 | Urban | 767.922 | 768.043 | -0.121 |
| Brush | 779.181 | 779.449 | -0.268 | Urban | 746.625 | 746.616 | 0.009 |
| Brush | 785.572 | 785.873 | -0.301 | Urban | 668.133 | 668.36 | -0.227 |
| Brush | 689.231 | 689.397 | -0.166 | Urban | 648.253 | 648.604 | -0.351 |
| Brush | 759.016 | 759.277 | -0.261 | Urban | 700.725 | 700.836 | -0.111 |
| Brush | 687.211 | 687.689 | -0.478 | Urban | 689.828 | 689.693 | 0.135 |
| Brush | 642.325 | 643.008 | -0.683 | Urban | 654.22 | 654.308 | -0.088 |

It is common for a Lidar dataset to have larger error residuals in areas with heavy brush or tall grass since the Lidar pulses often do not penetrate all the way to the ground, thus making it very difficult to define a ground surface in the point classification process. This is a limitation of Lidar data and caution should be used when using the Lidar data in these areas.

A summary of the residual error statistics between the survey data and the random Lidar surface at each survey point's horizontal coordinates is shown in Table 3. The mean difference between survey points and Lidar data is -0.187 ft, the negative value indicating that on average the Lidar data is slightly below the earth's surface as defined by the survey points.

Table 2. Summary Error Residual Statistics (Lidar Surface - Checkpoint Data)

| Statistic measures - Overall | | | |
|------------------------------|-----------------------------|------------|---|
| Value | Measure | App A ref. | Notes |
| 100 | Number of points | | Number of points used in analysis |
| -0.187 | Mean (ft) | N/A | Average elevation difference for all checkpoints. Overall Lidar values are below checkpoint values . |
| -0.186 | Median (ft) | N/A | Elevation difference for checkpoint in the middle of all checkpoint differences |
| 0.314 | Max (ft) | | Maximum elevation difference between checkpoints and Lidar derived elevations |
| -0.683 | Min (ft) | | Minimum elevation difference between checkpoints and Lidar derived elevations |
| 0.263 | RMSE (ft) | A.8.6.1 | Measure of how widely lidar values are dispersed from the checkpoint data of higher accuracy. Meets FEMA specifications for 2' contour mapping. |
| 0.186 | Standard Deviation (ft) | A.8.6.3 | Measure of how widely error values are dispersed from average. |
| < -0.746 > 0.372 | 3-sigma level (ft) | A.8.6.3 | Statistical outliers (elev diff > 3-sigma), or the Mean – 3 * Standar Deviation and the Mean + 3 * Standard Deviation. |
| -0.395 | Kurtosis | A.8.6.3 | Flatter than normal. |
| 0.025 | Skewness | A.8.6.3 | Skewed to the right of normal, this value is within the FEMA threshold of +/-0.5. |
| 0.035 | Variance (ft ²) | N/A | Variance of elevation differences for all checkpoints |

The individual RMSE of all cover types except Brush also meets the 0.303 ft (9.25cm) RMSE specification. The Forested and Urban cover types have the lowest RMSE values of 0.202 ft (6.150 cm) and 0.144 ft (4.384 cm) respectively. Areas in the Brush cover type have the highest RMSE of 0.332 ft (10.130 cm) indicating less accurate surface definition in this cover type. It is common for the Brush cover type to exceed RMSE specifications because the lidar returns often do not get recorded from the actual ground surface beneath the brush. This can happen either because the brush is too dense for the lidar to penetrate to the ground or because the brush is too low to the ground. When the brush is too low to the ground then there isn't enough time between the returns of a lidar pulse for both of the returns to get recorded by the sensor. This is referred to as vertical discrimination of the lidar sensor. The amount of vertical discrimination varies from sensor to sensor. A typical sensor has a vertical discrimination of 2-3 meters. This means that if the 1st return of a lidar pulse reflects off an object then the 2nd return must be at least 2-3 meters away from the 1st pulse. If there are any objects within the 2-3 meter distance then their reflections will not be recorded by the sensor. Therefore if the brush is within 2-3 meters of the ground then the return from the ground will not get recorded by the sensor.

Table 3. Summary of Error Residual Statistics for All the Checkpoints and for the Checkpoints Classified by Land Cover Type.

| Cover Type | RMSE (ft) | RMSE (cm) | Average Elevation Difference (ft) | Standard Deviation (ft) | Maximum Elevation Difference Value (ft) | Minimum Elevation Difference Value (ft) | Number of Checkpoints Used in Analysis |
|-------------------|-----------|-----------|-----------------------------------|-------------------------|---|---|--|
| All 5 Cover Types | 0.263 | 8.023 | -0.187 | 0.186 | 0.314 | -0.683 | 100 |
| Subtypes: | | | | | | | |
| BareEarth | 0.289 | 8.799 | -0.240 | 0.165 | 0.141 | -0.466 | 21 |
| High Grass | 0.312 | 9.512 | -0.268 | 0.164 | 0.030 | -0.576 | 22 |
| Brush | 0.332 | 10.130 | -0.298 | 0.152 | -0.014 | -0.683 | 16 |
| Forested | 0.202 | 6.150 | -0.117 | 0.169 | 0.127 | -0.468 | 21 |
| Urban | 0.144 | 4.384 | -0.027 | 0.145 | 0.314 | -0.351 | 20 |

FEMA sent out a memorandum in late September 2010 that updated the methodology for calculating the vertical accuracy of all land cover classes that are not open ground. Most non-ground land cover types do not have a normal error distribution, which is a requirement when calculating RMSE. The accuracy in non-ground cover types is referred to as supplemental vertical accuracy (SVA) and is calculated using the 95th percentile method as defined in the NDEP guidelines of 2004. The 95th percentile indicates that 95 percent of the errors in the dataset will have absolute values of equal or lesser value and 5 percent of the errors will be of larger value. FEMA lists the target SVA for 1-foot contour mapping as 0.60 ft. FEMA also states that one SVA category can test higher and another lower than the target SVA value so long as the overall consolidated vertical accuracy (CVA) for all land cover types meets the target. This SVA was calculated as an additional accuracy measurement for the Milwaukee, WI lidar dataset. Table 4 presents the results of this calculation. The bare earth cover type was calculated as well so that a comparison could be made for the relative amount of error in each cover type.

Table 4 Supplemental Vertical Accuracy of all land cover types.

| Cover Type | 95 th Percentile (ft) |
|-------------------------|----------------------------------|
| All 5 Cover Types (CVA) | 0.475 |
| Bare Earth | 0.456 |
| High Grass | 0.521 |
| Brush | 0.606 |
| Forested | 0.453 |
| Urban | 0.333 |

3.6 ACCURACY ASSESSMENT SUMMARY

The Milwaukee, WI lidar data meets the FEMA specifications for a normal distribution. The overall RMSE of 0.263 ft (8.023 cm) also meets the requirement to be less than 9.25 cm, which is based on the National Digital Elevation Program guidelines for 1-foot contour mapping. Individually, all of the ground cover categories, except Brush, meet the target 95th percentile value of 0.60 ft. The brush category is barely over the target at 0.606 ft.

4. QUALITY CONTROL REVIEW

The methodology Groundpoint presents here for reviewing the Lidar quality control implements the FEMA and FGDC guidelines (FEMA, 2003 and FGDC, 1998). Groundpoint coordinated with Milwaukee and Pictometry to obtain all available information.

4.1 Deliverables Review

4.1.1 Verify Pre-Flight Deliverables

Pictometry provided pre-flight deliverables including a map showing the collection area with planned flight lines, the collection plan, and information about times of high PDOP for the GPS equipment.

4.1.2 Verify Post-Flight Deliverables

Pictometry provided a metadata file for the collection that has information about the ellipsoid model and data processing procedures for processing the lidar data. Pictometry also provided information about the LIDAR system data report, the daily flight report, and ground control report. Pictometry did not provide a system calibration report.

4.1.3 Verify Mission Documentation

4.1.3.1 Calibration Report

There is no information about system calibration during acquisition. Groundpoint's accuracy assessment indicates that there do not appear to be any apparent system calibration issues impacting the quality of the final data products, and that the final data products are within FEMA standards for use in Floodplain Mapping.

4.1.3.2 PDOP

Pictometry provided PDOP information and charts for each mission.

4.1.3.3 Base Station

Pictometry provided base station and distance to base station information for each day.

4.1.3.4 Mission Report

There is no specific mission report, but most of the information was provided within the Daily Flight Logs and other documentation.

4.1.3.5 Flight Lines

Pictometry provided a shapefile of flightlines (see Figure 6).




Figure 6 shows the flightlines for the collection area.

4.2 General Data Review

Pictometry delivered the Lidar data in LAS format to in the summer of 2010. Groundpoint performed the QAQC on the ground points of the data set. Groundpoint used UNC's LASTools, QCoherent's LP360, and ESRI's ArcGIS software for all data processing.

4.2.1 Total Number of Points

The collection area consists of 319 tiles. UNC's Las2las tool, Command Line tools, and ESRI's 3D analyst tools were used to extract the point count and other information from each las tile. There are 781,464,149 ground points in the collection area out of 2,368,063,475 total points.

Number of Points

2,368,063,475 All points

781,464,149 Ground points

4.2.2 Collection Area

The collection area consists of 319 tiles that total 245 mi². The following figure shows the lidar tiles in the collection area.




Figure 7 shows the 319 lidar tiles and the boundary of groundpoints in the collection area.

4.2.2.1 Datum

Groundpoint confirmed the consistency of the geographic projection system (NAD 1927 State Plane Wisconsin South Zone) while developing the terrain and subsequently derived raster DEM, and hillshade layers.

4.2.2.2 Round-Off Check

Groundpoint checked 20 random tiles. All tiles have two decimal places for X, Y, and Z coordinate values.

4.2.2.3 Edge Consistency

A visual review of the hillshade layer confirmed that elevations were consistent across file edges. Profile tools were also used to randomly check consistency across file edges.

4.2.2.4 Mosaic/Hillshade

Groundpoint created a terrain for the collection area from a composite of the multipoints corresponding to the full set of LAS tiles. The terrain was used as the basis for creating a 5 ft DEM raster, which was itself used to create a hillshade (Figure 8). The hillshade was generated using an illumination angle of 45 degrees facing in a 315 degree cardinal direction (southeast), and allowed for visual assessment of edge consistency, completeness in the dataset, and artifacts



Figure 8 shows an example of the Hillshade displayed at 1:4000 scale. The hillshade was used to confirm edge consistency and to look for artifacts and systematic errors in the data. The area within the red circle shows proper removal of ground points from an overpass.

4.2.3 Complete Coverage

The data collected in the Milwaukee, WI area is complete. There are no gaps between flight lines or large data voids.

4.2.3.1 Metadata Complete

Pictometry provided metadata for this lidar collection.

4.3 Technical Data Review

4.3.1 Range of Elevations

The minimum and maximum elevation locations were extracted from the las tiles. The minimum elevation of 475.31 ft is located in a quarry in tile 258. The maximum elevation of 994.80 ft is located in the southwest corner of the collection area in what appears to be a landfill in tiles 310, 324, and 325.

Elevation Range

Min: 475.31 ft

Max: 994.80 ft

4.3.2 Bare Earth Point Density and Post Spacing

As discussed above, the 319 tiles in Madison County contained a total of 781,464,149 ground points (out of 2,368,063,475 total points), and covered an area of 245 mi². This equates to an average of 0.114 ground points per ft², and taking the square root of the reciprocal yields an average ground post spacing of 2.956 ft.

Point Spacing

Point Density = 0.114 ground points per ft²

Bare Earth Post Spacing = 2.956 ft

4.3.3 Void Areas

FEMA defines data voids as areas that are not within two times the required DEM posting of data points, which equates to 10m for the 2-foot contour interval accuracy standard. Data voids are acceptable over bodies of water or where points have been removed over man-made structures. Data voids are not acceptable with Lidar system malfunction or flight error. Data voids need to be flagged in areas where Lidar points have been removed due to dense vegetation. If the data voids in areas of dense vegetation are less than 1 acre then the voids may usually be

filled by interpolation. If the data voids are greater than 1 acre then cross sections must be cut to fill the void areas.

To create the void areas, the multipoints for the merged tiles were converted to rasters using ESRI's "Feature to Raster" tool with an output cell size of 32 ft (10 m). The rasters were reclassified so that raster cells with data values were reclassified to "NoData" and raster cells that did not have any values were reclassified to "1". The rasters were mosaicked together and converted to polygon. The result represented data void areas 10 m x 10 m or larger as polygons.

This void feature class was layered over the orthoimagery provided by Milwaukee from so it could be determined what was on the ground in each area (e.g., water, buildings, vegetation), and therefore whether the void was acceptable (e.g., water and buildings) or not (e.g., vegetation). This information was recorded for each void area in the Landcover field in the attribute table.

A total of 145,287 data voids were identified. There are 1,524 data voids that are larger than one acre. All of the voids larger than one acre are due to water, wetland, building, or bridge removal. There were 10 voids that were flagged for being in bare earth areas that were corrected by Pictometry.

4.3.4 Artifacts

Visual inspection of the Lidar data was done using a hillshade derived from a countywide, 5 foot resolution DEM of the Lidar ground points as well as a TIN generated on the fly using LP360 software. The hillshade was initially inspected at 1:5000 scale. Any anomalies (artifacts) in the data were investigated using the orthoimagery provided by Milwaukee and/or "bird's eye" oblique imagery from www.bing.com/maps, and the original all points lidar data. Artifacts were flagged if the change in elevation from the surrounding ground elevation was greater than +/- 3 feet.

There is no category of artifacts that stands out as signifying a problem with the dataset. No systematic artifacts were found. There were originally 179 artifacts flagged throughout the collection area. The artifacts ranged from misclassification of ground points on culverts (culverts were treated as bridges and all points removed), some bridges were not removed from the ground points when they should have been removed, some building points were left in the ground data, there were a few divots (low points) in the data ranging from 5ft – 20ft deep, and there were many low points from swimming pools. Pictometry corrected all of these artifacts in the individual lidar las tiles.

5. Summary

The lidar data for the Milwaukee, WI collection area meets all the FEMA specifications for floodplain mapping. The data passes the accuracy assessment test for RMSE and a normal distribution. The final dataset passes all quality control specifications and the dataset has adequate documentation from the collection vendor.

6. References

Bellamo, Doug A., Memorandum for Regional Risk Analysis Branch Chiefs, Procedure Memorandum No. 61 – Standards for Lidar and Other High Quality Digital Topography, September, 2010.

Geospatial Positioning Accuracy Standards, Part 3: National Standard for Spatial Data Accuracy, Federal Geographic Data Committee (FGDC), 1998, from <http://www.fgdc.gov/standards/projects/FGDC-standards-projects/accuracy/part3/chapter3>.

Guidelines for Digital Elevation Data Version 1.0, National Digital Elevation Program (NDEP), 2004, from http://www.ndep.gov/NDEP_Elevation_Guidelines_Ver1_10May2004.pdf

Map Modernization Guidelines and Specifications for Flood Hazard Mapping Partners, Appendix A: Guidance for Aerial Mapping and Surveying, Federal Emergency Management Agency (FEMA), April 2003, from http://www.fema.gov/plan/prevent/fhm/dl_cgs.shtm

Appendix A

The Lidar Checkpoint Survey Data

| Point # | Land cover type | Northing | Easting | Elevation |
|---------|-----------------|------------|-------------|-----------|
| 100 | 5 | 313336.238 | 2517720.063 | 822.094 |
| 101 | 2 | 314135.486 | 2528139.022 | 761.793 |
| 102 | 5 | 314849.722 | 2548602.411 | 679.874 |
| 103 | 1 | 315046.146 | 2565181.824 | 675.215 |
| 104 | 1 | 316822.537 | 2576903.284 | 702.828 |
| 105 | 3 | 324876.382 | 2577481.749 | 682.248 |
| 106 | 5 | 324870.292 | 2563130.423 | 668.126 |
| 107 | 4 | 321391.016 | 2547557.300 | 740.620 |
| 108 | 2 | 324047.820 | 2533517.702 | 728.027 |
| 109 | 3 | 324396.729 | 2526251.783 | 779.181 |
| 110 | 4 | 322319.610 | 2569989.677 | 670.209 |
| 118 | 1 | 348433.326 | 2518752.284 | 797.271 |
| 119 | 5 | 345898.998 | 2522050.614 | 775.918 |
| 120 | 2 | 350955.343 | 2529045.699 | 740.997 |
| 121 | 3 | 335694.214 | 2519233.063 | 785.572 |
| 122 | 4 | 337675.844 | 2531978.432 | 767.240 |
| 123 | 3 | 335118.563 | 2538006.473 | 689.231 |
| 124 | 2 | 335140.920 | 2544029.915 | 732.702 |
| 125 | 4 | 335184.555 | 2551532.628 | 715.013 |
| 126 | 1 | 335768.805 | 2555400.310 | 718.773 |
| 127 | 2 | 335685.537 | 2566952.760 | 691.788 |
| 128 | 5 | 335361.014 | 2572046.379 | 679.433 |
| 129 | 1 | 347303.471 | 2537180.180 | 721.531 |
| 130 | 3 | 344140.221 | 2546458.527 | 759.016 |
| 131 | 2 | 346616.335 | 2554567.719 | 735.508 |
| 132 | 4 | 345905.887 | 2561143.036 | 732.720 |
| 133 | 5 | 345789.110 | 2567901.480 | 717.497 |
| 134 | 3 | 350090.874 | 2575923.818 | 687.211 |
| 135 | 2 | 359809.434 | 2575378.913 | 651.684 |
| 136 | 5 | 355400.541 | 2571173.095 | 700.447 |
| 137 | 2 | 356775.437 | 2560688.082 | 669.936 |
| 138 | 5 | 355847.517 | 2548798.703 | 741.839 |

2010 Lidar Accuracy Assessment and Quality Control Report
December 2, 2010

| | | | | |
|-----|---|------------|-------------|---------|
| 139 | 1 | 356107.504 | 2541792.469 | 765.984 |
| 140 | 2 | 357601.192 | 2527741.686 | 754.133 |
| 141 | 4 | 354160.584 | 2518819.268 | 826.284 |
| 142 | 1 | 361800.215 | 2531871.420 | 784.056 |
| 143 | 4 | 361618.294 | 2552535.684 | 657.703 |
| 144 | 3 | 362734.798 | 2570242.364 | 642.325 |
| 145 | 2 | 366022.703 | 2519354.623 | 730.938 |
| 146 | 5 | 366262.106 | 2527437.264 | 819.130 |
| 147 | 5 | 366574.656 | 2538223.092 | 732.768 |
| 148 | 1 | 368897.450 | 2560842.718 | 615.434 |
| 149 | 4 | 365050.311 | 2571671.746 | 627.682 |
| 150 | 3 | 362714.448 | 2545066.232 | 709.930 |
| 151 | 4 | 375699.392 | 2516987.799 | 758.203 |
| 152 | 4 | 377155.545 | 2548255.976 | 659.512 |
| 153 | 2 | 379819.720 | 2559499.266 | 598.696 |
| 154 | 1 | 374620.461 | 2537153.756 | 689.414 |
| 155 | 5 | 376807.178 | 2527349.040 | 765.041 |
| 156 | 5 | 380480.803 | 2530905.384 | 708.497 |
| 157 | 5 | 380739.902 | 2544696.742 | 597.307 |
| 158 | 4 | 387953.756 | 2538782.976 | 700.039 |
| 159 | 2 | 387396.348 | 2526775.996 | 757.803 |
| 160 | 3 | 386520.565 | 2520451.501 | 721.193 |
| 161 | 2 | 390575.339 | 2550993.247 | 680.426 |
| 162 | 4 | 397307.580 | 2526904.834 | 717.446 |
| 163 | 5 | 397807.395 | 2517161.459 | 767.922 |
| 164 | 1 | 385063.975 | 2546198.386 | 683.564 |
| 165 | 1 | 387176.218 | 2562505.247 | 587.729 |
| 170 | 4 | 396931.442 | 2568737.082 | 670.641 |
| 171 | 4 | 397158.345 | 2561838.000 | 675.040 |
| 172 | 1 | 397618.214 | 2543397.076 | 701.290 |
| 173 | 1 | 400991.697 | 2551731.513 | 703.863 |
| 174 | 1 | 398958.924 | 2535859.050 | 756.369 |
| 175 | 5 | 402609.767 | 2527282.851 | 746.625 |
| 176 | 5 | 405255.908 | 2555676.824 | 668.133 |
| 177 | 2 | 406090.648 | 2537895.751 | 671.328 |
| 178 | 4 | 407989.730 | 2519887.034 | 708.640 |
| 179 | 2 | 414006.454 | 2523155.038 | 716.745 |
| 180 | 2 | 408085.792 | 2538172.757 | 662.567 |
| 181 | 3 | 407865.319 | 2551844.913 | 649.371 |
| 182 | 3 | 407175.819 | 2558167.412 | 644.932 |
| 183 | 1 | 410800.007 | 2564049.035 | 656.870 |

2010 Lidar Accuracy Assessment and Quality Control Report
December 2, 2010

| | | | | |
|-----|---|------------|-------------|---------|
| 189 | 4 | 422588.821 | 2560015.400 | 706.116 |
| 190 | 4 | 422907.393 | 2560103.330 | 705.677 |
| 191 | 5 | 415162.626 | 2558596.500 | 648.253 |
| 192 | 1 | 419035.252 | 2558752.128 | 691.083 |
| 193 | 1 | 420066.038 | 2549006.011 | 654.598 |
| 194 | 2 | 419792.082 | 2544616.217 | 694.783 |
| 195 | 3 | 419907.654 | 2536933.233 | 704.144 |
| 196 | 2 | 418600.775 | 2529806.075 | 737.726 |
| 197 | 2 | 419497.967 | 2520270.590 | 782.428 |
| 198 | 4 | 419287.348 | 2517998.953 | 757.500 |
| 199 | 4 | 430613.093 | 2553885.037 | 659.464 |
| 200 | 3 | 434219.129 | 2548616.919 | 651.937 |
| 201 | 5 | 427814.721 | 2545793.966 | 700.725 |
| 202 | 5 | 430334.012 | 2541534.458 | 689.828 |
| 203 | 1 | 430584.433 | 2537984.572 | 692.402 |
| 204 | 2 | 432969.523 | 2526923.117 | 750.235 |
| 205 | 3 | 429067.995 | 2524874.211 | 733.484 |
| 206 | 4 | 430057.393 | 2517550.938 | 743.911 |
| 207 | 3 | 435103.733 | 2563884.982 | 679.358 |
| 208 | 1 | 432877.039 | 2564166.941 | 685.571 |
| 209 | 1 | 438033.365 | 2559474.853 | 662.188 |
| 210 | 1 | 438682.236 | 2550585.239 | 689.820 |
| 211 | 5 | 439545.221 | 2543013.115 | 654.220 |
| 212 | 3 | 440768.513 | 2532524.281 | 684.631 |
| 213 | 4 | 438942.931 | 2527051.496 | 779.074 |
| 214 | 2 | 439721.139 | 2525690.659 | 753.887 |
| 215 | 2 | 440426.271 | 2517526.447 | 769.169 |